

18681 Lake Drive East Chanhassen, MN 55317 952-607-6512 www.rpbcwd.org

MEMORANDUM

TO: Terry Jeffery

FROM: Mathieu Nicklay

DATE: 29 September 2022

RE: Status of August 2022 non-compliant sites

8/03 Permit # 2021-073 3981 Hillcrest Road

Perimeter controls damaged allowing sediment to escape site on east perimeter. Disturbed soil outside of silt fence.

Status: Perimeter control issues remain uncorrected

8/08 Permit # 2021-034 18200 Honeysuckle Lane

Perimeter controls displaced in back yard of lot.

Status: Under review. Perimeter controls have been removed in preparation for sod placement.

08/11 Permit # 2021-067 Ridgeview Church Playground

Small area of disturbed soil needs to be stabilized.

Status: Landscape blanket and seed have been placed.

08/15 Permit # 2020-066 Chase Bank – Eden Prairie

Perimeter control needed along curb at parking lot entrance. Two unprotected inlets in SW corner of lot

Status: Construction has been completed on this project. All disturbed soils are stabilized and temporary BMPs have been removed.

08/15 Permit # 2022-017 Oak Point Elementary Circulation Upgrades North

Perimeter controls missing along some curb lines. Several catch basin inlets are unprotected.

Status: All issues have been corrected.



18681 Lake Drive East Chanhassen, MN 55317 952-607-6512 www.rpbcwd.org

08/15 Permit # 2020-031 Prairie Heights

General maintenance of perimeter controls is needed. Sediment accumulating on streets.

Status: All issues have been corrected.

08/16 Permit # 2020-045 Bluffs at Lake Lucy

Silt fence needs general maintenance to address damaged areas. Heavy tracking of sediment.

Status: All issues have been corrected.

08/19 Permit # 2022-018 EP High School Stadium Improvements 2022

No protection on any catch basin inlet. Protection must be installed on each catch basin after removal of accumulated sediment. Heavy accumulation of sediment in several catch basins. Sediment must be removed and catch basins protected until site is stabilized

Status: All issues have been corrected.

08/19 Permit # 2022-002 Minnetonka High School, New Vantage/Momentum Building

Breach in silt fence along Cty Rd 101 allowing sediment to flow onto sidewalk.

Status: All issues have been corrected.

08/19 Permit # 2019-024 Conifer Heights

Catch basin silt bags need to be emptied and maintained.

Status: All issues have been corrected.

08/30 Permit # 2022-011 Dahiya Home Construction

Silt fence needs maintenance.

Status: All issues have been corrected.